

Situated in The

Month:

Page:

1111	IVIZ	IVIS
1" iron pipe fd.	1/2" iron pipe fd.	3/4" iron pipe fd.
@ 30.15' from C.L.	0.23' west of	@ 30.71' from C.L.
(MP, not on R/W)	property line (n/s)	(not on R/W)
and used for	and used for	and used for
property line (n/s)	property line (e/w)	property line (n/s)
		5/8" iron pin set R/W
		(30.92' from C.L. c.)
M4	M5	M6
1/2" iron pipe fd.	2" iron pipe with	5/8" iron pin fd.
@ 29.56' from C.L.	damaged cap fd.	@ 26.11' from C.L.
(not on R/W)	south 2.30', east 2.85'	(MP, not on R/W)
and used for	5/8" iron pin set R/W	and not used
property line (n/s)	(30.00' from C.L.)	in this survey