


RE: Parcel 9 - 36628 Vine Street, East Lake, OH

REG ID	CLIENT ID	LOCATION	COLOR
08WB-07119	LAK2PCL9#21	2nd Flr Rear Office Corner Joint	Cream
Texture/Description: Solid/Plasterboard Joint			
Chrysotile: 2% Tremolite: 0% Anthophyllite: 0%			
TOTAL ASBESTOS: 2%			
Amosite: 0% Actinolite: 0% Crocidolite: 0%			
Cellulose: 0% Fiber Glass: 0% Others: 0% Filler/Binder: 98%			

REG ID	CLIENT ID	LOCATION	COLOR
08WB-07120a	LAK2PCL9#22	2nd Flr Stairway Center Ceiling	Grey
Texture/Description: Solid/Plaster			
Chrysotile: 0% Tremolite: 0% Anthophyllite: 0%			
TOTAL ASBESTOS: 0%			
Amosite: 0% Actinolite: 0% Crocidolite: 0%			
Cellulose: 2% Fiber Glass: 0% Others: 3% Filler/Binder: 95%			

REG ID	CLIENT ID	LOCATION	COLOR
08WB-07120b	LAK2PCL9#22	2nd Flr Stairway Center Ceiling	White
Texture/Description: Solid/Top Coat			
Chrysotile: 0% Tremolite: 0% Anthophyllite: 0%			
TOTAL ASBESTOS: 0%			
Amosite: 0% Actinolite: 0% Crocidolite: 0%			
Cellulose: 0% Fiber Glass: 0% Others: 0% Filler/Binder: 100%			

Analytical Method: Polarized light microscopy using dispersion staining (EPA-600/M4-82-020). PLM should not be used to demonstrate the absence of asbestos in floor tiles. All samples will be held for sixty (60) days unless otherwise requested. This report relates only to items tested and makes no statement as to the contents of surrounding materials. Multi-layered material which have distinct and separable layers shall be reported separately. This report shall not be reproduced, except in full, without written permission. The results of this report should not be used as an endorsement for NVLAP or any other government agency.

Analyzed by: 
Tina Long