SOIL PROFILE
MEDINA COUNTY
MED 42 26.11
CUY 42 1.00
OHIO STATE HIGHWAY
TESTING LABORATORY
COLUMBUS OHIO

4
27

NOTE For cross section at Sta 468+00, see sheet 16

Hayfield

Poorly drained area

NOTE Creek flowing on sandy silt and sand with some gravel

Wet area

Hayfield

Field

Pasture

Woods

℄, Proposed U.S.R. 42

Holly Creek

Hayfield

Poorly drained area

NOTE This was pools of standing water occuring throughout the poorly drained area 3/26/62

Hayfield

Field

Pasture

Weeds

454 455 460 465 470 475 480 484

PROFILE AS REVISED 3-25-63

Sod=0.5' 21 Refusal (Hand auger) (Boulders)

100 Rt Sod CF 23 17 Refusal (Hand auger)

℄ Sod=0.5' 25 17 Refusal (Hand auger) (Boulders)

Brown and grey sandy silt with stone fragment

℄ TS=0.5' 22 1- 14 14

℄ TS=0.5' 22 15 23 9 Hole caved in at elev

℄ Sod 0.5' 6 16 15 Grey silty sand with gravel and stone fragment 15 17 Hole caved in at elev 1091.0 (hole squeezed in at elev 1089.0')

95 Rt TS 0.5' 19 16 20 16 17

95 Lt 95 Rt 17 7 16 16 18 16 13 13 15

℄ W 39 Refusal (Hand auger)

℄ 15 12 5 13

℄ 80 16 14

℄ ℄ 15W 30 15 Refusal (Hand auger)

95' Rt 17 15 14

75' Rt 21 17 16

1110 1100 1090 1080 1070 1060

454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484