


**Situated in the city of Mentor, County of Lake and State of Ohio
and known as being part of the Blake Lot, Tract No. 5, Township 10
North, Range 9 West of the Connecticut Western Weserve Survey.
March 2010 Scale 1"=30'**



Basis of Bearings:
Per the R/W Plans for Reynolds Road LAK - 306 - 7.12
Elevations based on LAK - 306 - 7.12 Utility Plans


LAND DESIGN CONSULTANTS
www.LDCinc.net

ENGINEERS PLANNERS SURVEYORS

9025 Osborne Drive, Mentor, Ohio 44060
TEL: (440) 255-8133 FAX: (440) 255-8140
(440) 354-6938 FAX (440) 255-9575

DATE 4/01/10
SCALE: HOR. 1"=30'
VERT. _____
FILENAME Lot Split Sur.
COMPUTER S
TAB NAME Split

SHEET	OF
1	1
CONTRACT No.	
OSAIR1-1001	



Certification:

I hereby certify that this plat was prepared from a field survey made under my direct supervision. Monuments were found or set as indicated. Dimensions are expressed in feet and decimal parts thereof. All of which are correct to the best of my knowledge and belief. This plat was prepared in accordance with the provisions of Chapter 4733-37 of the Ohio Administrative Code.

Robert A. Brown

Richard A. Thompson, Jr., P.S. #7388
411.10