



Station	Cut (Cu.Yds)	Fill (Cu.Yds)
Sta. 300+00 to Sta. 310+00	Cut = 895.4	Fill = 226.5
Sta. 310+00 to Sta. 320+00	Cut = 560.5	Fill = 162.8
Sta. 320+00 to Sta. 330+00	Cut = 780.8	Fill = 319.2
Sta. 330+00	Cut = ...	Fill = ...

Station	Cut (Cu.Yds)	Fill (Cu.Yds)
697	C=4.1, F=4.0	
698	C=8.4, F=13.5	
699	C=13.7, F=15.3	
699	C=19.1, F=11.5	
699	C=19.0, F=11.1	
699	C=12.0, F=13.7	
699	C=9.3, F=24.5	
699	C=6.9, F=44.3	
699	C=4.3, F=43.9	
699	C=3.0, F=75.9	
700	C=2.5, F=20.0	
700	C=2.6, F=14.3	
700	C=4.1, F=5.4	
701	C=5.9, F=3.0	
702	C=6.2, F=2.1	
701	C=6.8, F=18.1	
701	C=7.1, F=19.4	
701	C=6.7, F=21.5	
701	C=5.7, F=23.6	
700	C=5.3, F=23.1	
700	C=5.6, F=23.3	
700	C=7.0, F=14.4	
700	C=8.9, F=10.4	
700	C=9.3, F=23.1	
700	C=9.5, F=42.8	
700	C=9.9, F=35.1	
700	C=8.1, F=50.1	
700	C=5.5, F=60.2	
700	C=6.5, F=48.5	
700	C=7.1, F=16.7	
700	C=18.9, F=0.6	
699	C=12.4, F=9.8	
698	C=8.5, F=17.8	
697	C=2.0, F=29.7	
696	C=13.1, F=123.1	
696	C=2.0, F=115.4	
696	C=4.4, F=10.7	
696	C=5.5, F=...	