



Station	Cut (Cu.Yds.)	Fill (Cu.Yds.)
From Sta. 80 to Sta. 90	Cut = 569.1	Fill = 571.2
From Sta. 90 to Sta. 100	Cut = 556.0	Fill = 217.0
From Sta. 100 to Sta. 110	Cut = 692.8	Fill = 317.9
From Sta. 110 to Sta. 115	Cut = 580.0	Fill = 195.0

Station	Cut (Cu.Yds.)	Fill (Cu.Yds.)
6870	C = 7.7	F = 26.7
6870	C = 6.7	F = 29.1
6870	C = 11.2	F = 20.7
6870	C = 21.3	F = 0.3
6870	C = 28.4	F = 0.0
6870	C = 33.1	F = 92.2
6870	C = 60.2	F = 38.9
6870	C = 86.5	F = 0.6
6870	C = 86.1	F = 28.1
6870	C = 70.7	F = 52.8
6870	C = 65.2	F = 60.2
6870	C = 55.0	F = 64.4
6870	C = 50.6	F = 69.6
6870	C = 35.0	F = 61.1
6870	C = 38.5	F = 27.2
6870	C = 65.9	F = 13.7
6870	C = 77.8	F = 8.3
6870	C = 73.0	F = 13.1
6870	C = 57.0	F = 27.8
6870	C = 48.5	F = 31.1
6870	C = 44.8	F = 25.0
6870	C = 59.9	F = 11.1
6870	C = 54.4	F = 19.3
6870	C = 37.2	F = 40.4
6870	C = 41.7	F = 34.1
6870	C = 38.5	F = 41.3
6870	C = 31.3	F = 60.4
6870	C = 47.4	F = 45.6
6870	C = 72.2	F = 30.6
6870	C = 105.0	F = 15.7
6870	C = 122.6	F = 0.0
6870	C = 95.2	F = 23.9
6870	C = 79.3	F = 24.8
6870	C = 59.6	F = 41.5
6870	C = 15.6	F = 85.0
6870	C = 18.0	F = 48.7
6870	C = 60.6	F = 5.2
6870	C = 90.6	F = 0.9
6870	C = 85.2	F = 8.7