Proposal Addendum For LAK-2-3.32; PID 13486 Project 080597

Revise the following Items:

| Ref. No. | Item Number | Quantity | Unit Description | |
|----------|-------------|----------|------------------|--|
| 41 | 608E4900 | 22 | Each | Curb Ramp |
| 425 | 614E13000 | 225 | CY | Asphalt Concrete for Maintaining Traffic |
| 448 | 616E10000 | 3155 | MGA L | Water |

Delete the following items:

| Ref. No. | Item Number | Quantity | Unit | Description |
|----------|-------------|----------|------|-----------------------------------|
| 401 | 410E12000 | 480 | CY | Traffic Compacted Surface, Type A |

Added Items:

| Ref. No. | Item Number | Quantity | Unit | Description |
|----------|-------------|----------|------|--------------------------------------|
| 1064 | 608E52000 | 75 | SF | Curb Ramp |
| 1065 | 613E41300 | 66 | CY | Low Strength Mortar Backfill, Type 2 |

Delete the following note:

Sheet 48/1679 and Sheet 56B/1679 Item 614, Maintaining Traffic (Estimated Quantities).

Revise the following notes:

Sheet 53/1679 and Sheet 56G/1679 Unsuitable Soils at Crossover Locations should read:

Unsuitable soils may be encountered at crossover locations. The following quantities are provided for use by the contractor, if crossovers are utilized.

| 395 | 204E13000 | 1530 | $\mathbf{C}\mathbf{Y}$ | Excavation of Subgrade |
|-----|-----------|------|------------------------|----------------------------------|
| 396 | 204E30010 | 1530 | $\mathbf{C}\mathbf{Y}$ | Granular Material, Type B |
| 399 | 304E20000 | 815 | $\mathbf{C}\mathbf{Y}$ | Aggregate Base |
| 404 | 451E15500 | 6563 | SY | 11" Reinforced Concrete Pavement |

Sheet 52/1679 and Sheet 56F/1679 Drainage Items During Construction:

Delete the wording "as directed by the engineer".

Sheets 17B and 17C have been revised and linked to this addendum in order to include changes to the concrete median barrier details.