


NOTES:

1. All Pier 2 Concrete Surfaces Shall Be Sealed With An Epoxy-Urethane Sealer.

LEGEND:



- Existing Areas To Be Repaired Per Item 519-
 Patching Concrete Structure.

CT Consultants, Inc.
 Engineers • Architects • Planners
 Willoughby • Mentor • Columbus • North Canton • Canton 9/20

PIER REPAIR
 BRIDGE NO. LAK-2-0451
 S.R. 2 UNDER STEVENS BLVD.
 LAKE COUNTY

DESIGNED	DRAWN	TRACED	CHECKED	REVIEWED DATE	REVISED
I.A.S.	I.A.S.	I.A.S.	J.P.R.	J.E.A. 2-25-94	