



End Area		Cu Yds	
Cut	Fill	Cut	Fill
6	68		
		11	137
6	85		
		14	171

Sta. 81+50 to 84+00