



elevations are existing finished grades checked in the field on March 24 2009 and as of that date the lot corner iron pins were existing and that the survey is correct to the best of my knowledge and belef.

DE M 3-4-89 P.S.# 8249
NAME DATE REG. No.

38879 MENTOR AVENUE SUITE A WILLOUGHBY OHIO 44094 440-602-9071



ENGINEERING and SURVEYING

Civil Engineering Land Surveying

SHEET CONTENT

AS-BUILT PLAN FOR VINCENT HOMES LLC

*15 MINNEWA WA ROAD* 

P.P.#33-A-001-0-00-050-0
BEING SUBLOT 14 IN BLOCK 2
OF THE ELWORTHY
HELWICK COMPANY'S
LAKE SHORE BOULEVARD
ESTATES ALLOTMENT
PLAT VOLUME D, PAGE 55
LOCATED ON MINNEWAWA ROAD
IN THE VILLAGE OF TIMBERLAKE
COUNTY OF LAKE
STATE OF OHIO

REVISIONS			
NO.	DATE	DESCRIPTION	BY
	<del></del>		
<del></del>			
	<del></del>		
	<u>-</u>		
		· · · · · · · · · · · · · · · · · · ·	

HORIZ. SCALE	VERT. SCALE	
1*=20*		
DRAWN BY	DATE	
α	3/4/09	
CHECKED BY	DRAWNG NO	
SRL	ASBUILT	
JOB NO	SHEET	
172018	1 OF 1	