



STEEL LIST				
MARK	SIZE	SHAPE	LENGTH	NO.
H2b	1/2" φ	St'right	15'-3"	8
H2c	1/2" φ	Bent	4'-0 3/8"	8
P6a	3/8" φ	"	9'-0 1/2"	8
P6b	3/8" φ	"	6'-2"	12
P6c	3/8" φ	"	4'-3 1/2"	8
P6d	3/8" φ	"	9'-0 1/2"	8
P6e	3/8" φ	"	6'-2"	12
P6f	3/8" φ	"	4'-3 1/2"	8
P6g	3/8" φ	St'right	4'-2"	2
P6h	3/8" φ	"	8'-6"	2
P6i	3/8" φ	"	11'-4"	10
P6j	3/8" φ	"	11'-4"	10
P6k	3/8" φ	"	13'-0"	4
P6l	3/8" φ	"	4'-9"	2
P6m	3/8" φ	"	3'-8"	2
P6n	3/8" φ	"	7'-5"	2
P6o	3/8" φ	"	10'-4"	8
P6p	3/8" φ	"	10'-4"	10
P6q	3/8" φ	"	12'-2"	4
P6r	3/8" φ	"	5'-2"	2
M6a	3/8" φ	Bent	12'-4"	8
M6b	3/8" φ	"	11'-4"	8
M6c	3/8" φ	"	11'-4"	4
M6d	3/8" φ	"	12'-4"	8
M6e	3/8" φ	"	11'-9"	4
M6f	3/8" φ	"	12'-5"	4
M6g	3/8" φ	"	8'-7"	10
M6h	3/8" φ	"	8'-2"	8
M6i	3/8" φ	"	8'-0"	8
M6j	3/8" φ	"	8'-7"	8
M6k	3/8" φ	"	8'-2"	6
M6l	3/8" φ	"	6'-0"	20
M6m	3/8" φ	St'right	12'-5"	10
M6n	3/8" φ	"	10'-5"	6
M6o	3/8" φ	"	8'-5"	2
M6p	3/8" φ	"	11'-8"	8
M6q	3/8" φ	"	9'-9"	6
A7a	1" φ	Bent	30'-9"	178
B7a	3/8" φ	St'right	15'-6"	88
C6a	3/8" φ	Bent	18'-0"	88
D4a	3/8" φ	St'right	12'-0"	88
E4a	3/8" φ	"	60'-8"	62

SECTION E-E & F-F

SECTION C-C & D-D

SECTION G-G & H-H

VIEW K-K & L-L

VIEW M-M & N-N

SECTION A-A & B-B

BAR BENDING DIAGRAMS

3

Sta. 11 + 90