



BENCH MARK #5
TOP NW CORNER STONE SLAB
ON WEST WALL OF STEPS
STA. 83+10± 77± RT.
ELEV. 686.73

FULL DEPTH PAVEMENT REPAIR
AS PER SECTION 603.09 OF
THE CONSTRUCTION AND
MATERIALS SPECIFICATIONS.

EXISTING PAVEMENT
TO BE REMOVED

| Station | Elevation | Notes | Station | Elevation |
|---------|-----------|-------|---------|-----------|
| 83+00 | 676.71 | | 85+00 | 679.05 |
| 676.70 | | | 679.80 | |
| 676.81 | | | 680.62 | |
| 676.96 | | | | |
| 677.18 | | | | |
| 677.45 | | | | |
| 677.78 | | | | |
| 678.16 | | | | |
| 678.98 | | | | |
| 679.80 | | | | |
| 680.62 | | | | |
| 83+00 | 676.71 | | 86+00 | 680.63 |

| Station | Elevation | Notes | Station | Elevation |
|---------|-----------|-------|---------|-----------|
| 83+00 | 676.71 | | 85+00 | 679.05 |
| 676.70 | | | 679.80 | |
| 676.81 | | | 680.62 | |
| 676.96 | | | | |
| 677.18 | | | | |
| 677.45 | | | | |
| 677.78 | | | | |
| 678.16 | | | | |
| 678.98 | | | | |
| 679.80 | | | | |
| 680.62 | | | | |
| 83+00 | 676.71 | | 86+00 | 680.63 |

| Station | Elevation | Notes | Station | Elevation |
|---------|-----------|-------|---------|-----------|
| 83+00 | 676.71 | | 85+00 | 679.05 |
| 676.70 | | | 679.80 | |
| 676.81 | | | 680.62 | |
| 676.96 | | | | |
| 677.18 | | | | |
| 677.45 | | | | |
| 677.78 | | | | |
| 678.16 | | | | |
| 678.98 | | | | |
| 679.80 | | | | |
| 680.62 | | | | |
| 83+00 | 676.71 | | 86+00 | 680.63 |