


EXISTING PAVEMENT RESURFACING

NOTE:  
ELEVATIONS ARE TOP OF PAVEMENT ELEVATIONS.



INTERSECTION DETAILS  
BOWHALL ROAD - BACON ROAD

LAK - 20 - 18.72