


**PLAT OF SURVEY AND CONSOLIDATION OF LANDS FOR MARKO HOME SOLUTIONS, LLC**  
 PPN's 16-A-002-B-00-037-0 and 16-A-002-B-00-038-0

Situated in Original Mentor Township Lot No. 5, Tract No. 4 and being part of Sublot No. 70 and all of Sublot No. 71  
 of Brentwood Subdivision #2 as recorded in Volume H Page 35 of Lake County Plat Records

**Notes:**

1. Basis of bearings: C/L Middlesex Road S 06°00'00"W.
2. (d)=deed, (c)=calculated, (m)=measured, (p)=plat
3. rebar set are 5/8" x 30" rebar with "Harrison 7002" survey cap
4. References
  - A. Plat H-35
  - B. Plat H-34
  - C. deeds of record
5. No encroachments noted.
6. This plat was prepared without benefit of a title examination and is subject to the results that an independent title examination might reveal.

**CURVE DATA:**  
 C-1  
 A=6.13' R=666.00'  
 CH=S 05°28'24"W, 6.13'



I, the undersigned, hereby certify that the boundary survey represented by this plat and all monumentation set were conducted in accordance with the specifications set forth in Chapter 4733-37 of the Ohio Administrative Code. Surveyed July, 2022



*Douglas F. Harrison*  
 Douglas F. Harrison, P.S.  
 Registered Surveyor No. 7002, State of Ohio, for  
 HARRISON SURVEYS, LLC  
 236 Burton Street, Fairport Harbor, Ohio 44077  
 Ph/text 440.477.9525  
 Email Harrisonsurveysllc@gmail.com

