
W:\2019\19100\Consolidation\19100 20201026.dwg, 10/26/2020 2:08:10 PM, Adobe PDF CONSULTING GROUP, INC. Civil Engineers - Surveyors - Land Planners 114 Tyler blvd., Mentor, Ohio 44060, 440.205.1260 FAX 440.205.1262 www.BarringtonCGI.com Barrington 30.00' CITY OF MENTOR I6-B-062-0-00-022-0 DOC. #I996R034396 OEDICATED VOL. 29, PG. 16) 160.09' 248.89' 684.15' 744.67' 8000.00' 650.00' CURVE TABLE SURVEY REFERENCES:
PLAT OF SURVEY FOR 8989 TYLER BOULEVARD BY
McSTEEN & ASSOCIATES DATED 4/09/07 9079 TYLER ROAD LLC 16-B-062-0-00-023-0 DOC. #2004R027771 80.13' 125.85' 342.29' 372.60' 160.00' 247.50' 683.94' 744.40' Original Mentor Township Lot No. 3, Tract No. 7 and State of Ohio, and known as being part of Situated in the City of Mentor, County of Lake CERTIFICATION:

I HEREBY CERTIFY THAT AN ACTUAL BOUNDARY SURVEY WAS PREPARED BY ME ON THE jeth DAY OF jec. 2019, AND THAT THE SURVEY IS IN ACCORDANCE WITH THE OHIO REVISED CODE CHAPTER 4733-37, MINIMUM STANDARDS FOR BOUNDARY SURVEYS IN THE STATE OF OHIO. PERMANENT MONUMENTS WERE FOUND, OR SET AT ALL LOCATIONS SHOWN HEREON. ALL DIMENSIONS GIVEN ARE EXPRESSED IN FEET OR DECIMAL PARTS THEREOF. BEARINGS ARE TO AN ASSUMED MERIDIAN AND ARE SHOWN TO INDICATE ANGLES ONLY. ALL PINS SET ARE 5/8" DIA., 30" LONG REBAR WITH CAP MARKED "NOVAK 7507". AREA SUMMARY: I HEREBY CERTIFY THAT, THIS PLAT WAS PREPARED BY ME AND IS CORRECT TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF." PPN. 16-B-059-0-00-015-0 - 22.2683 ACRES PPN. 16-B-059-0-00-027-0 - 4.0717 ACRES CONSOLIDATED PARCEL - 26.3400 ACRES GRAPHIC SCALE Jun!



MONUMENT BOXES FOUND COULD NOT BE OPENED. POINTS RE-ESTABLISHED BY REFERENCE DRILL HOLES FOUND.

BUYERS PRODUCTS COMPANY

9049 TYLER BOULEVARD MENTOR, OHIO 44060

CONSOLIDATION PLAT

JIM LINES

9049 TYLER BOULEVARD **MENTOR, OHIO 44060** CELL:440-415-2442

Barrington CONSULTING GROUP, INC.

9114 TYLER BLVD., MENTOR, OHIO 44060 PHONE 440.205.1260 FAX 440.205.1262 www.BarringtonCGI.com

