


REVISIONS	BY

**Barrington**  
**CONSULTING GROUP, INC.**  
 9114 TYLER BLVD., MENTOR, OHIO 44060  
 PHONE 440.205.1260 FAX 440.205.1262  
 BCG@BarringtonCGL.com

**THE LORDIN GROUP**  
**PETER DI NUNZIO**  
 9093 LAKESHORE BLVD.  
 MENTOR, OHIO 44060  
 440-257-6630

**BOUNDARY SURVEY**  
 9093 LAKESHORE BLVD.  
 MENTOR, OHIO 44060



DRAWN  
**WSO**  
 CHECKED  
**DWN**  
 DATE  
**JUNE 18, 2007**  
 SCALE  
**1" = 50'**  
 JOB NO.  
**07075**  
 SHEET



**CERTIFICATION:**  
 I HEREBY CERTIFY THAT AN ACTUAL BOUNDARY SURVEY WAS PREPARED BY ME ON THE 18th DAY OF JUNE 2007, AND THAT THE SURVEY IS IN ACCORDANCE WITH THE OHIO REVISED CODE CHAPTER 4733-37, MINIMUM STANDARDS FOR BOUNDARY SURVEYS IN THE STATE OF OHIO. PERMANENT MONUMENTS WERE FOUND, OR SET AT ALL LOCATIONS SHOWN HEREON. ALL DIMENSIONS GIVEN ARE EXPRESSED IN FEET OR DECIMAL PARTS THEREOF. BEARINGS ARE TO AN ASSUMED MERIDIAN AND ARE SHOWN TO INDICATE ANGLES ONLY. ALL PINS SET ARE 5/8" DIA., 30" LONG REBAR WITH CAP MARKED "NOVAK 7507".

I HEREBY CERTIFY THAT, THIS PLAT WAS PREPARED BY ME AND IS CORRECT TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF.

DAVID W. NOVAK, P.S. No. 7507



Situated in the City of Mentor, County of Lake and State of Ohio and known as being part of Lot 5, in Tract 11 Bearings used herein are to denote angular relationship only and do not represent true north.