



End Area	Cu. Yd.	
	cut	Fill
121	250	188
658		580
116	376	45
803		946
173	696	0
908		1246
154	700	
811		1297
138	701	
719		1327
121	732	

Sta. 48+00

Sta. 48+00