



End Area		Cu. Yds.	
Cut	Fill	Cut	Fill
		135.78	
		1023.5	
		1403.8	
		345.0	
		1255.4	
		1031.6	
		1167.2	
		504.7	

Sta 20+0 to Sta 20+50