

SCHADE SURVEYING COMPANY



4043 Erie Street
Willoughby, Ohio
440-951-6454

PK nail set at angle
by reference points
from 1918 san sewer records
and field notes 1289.75 Record
1270.12 Obs pipe to PK nail

Survey for Hegfield
50 Casement Avenue
Painesville, Ohio
Drawing Name Hegfield.zak
Field Book 130, Page 12
January 2010

Scale one inch equals 60 feet
File No. 10-1992


Bearings are based on the
Centerline of Casement Avenue being
North 00 degrees 07' 50" East



Casement Avenue 56'

1270 12' centerline to angle

N 00°07'50" E 408.41 Observed & used



East Main Street 60'

one inch iron pipe
in box found & used