





Seeding Dates	Species	Lb./1,000 ft. ²	Per Aq.
March 1 to August 15	Oats Tafi Feacus Annual Ryagrass	3 · 1 1	4 bushet 40 lb. 40 lb.
	Perennial Ryegrass Tall Fescue Annual Ryegrass	1 1 1	40 lb. 40 lb. 40 lb.
August 16 to November 1	Rye Tali Fescue Annual Ryegrass	3 1 1	2 bushel 40 lb. 40 lb.
	Wheat Tall Fescue Annual Ryegrass	3 1 1	2 bushei 40 lb. 40 lb.
	Perennial Ryegrass Tall Fescue Annual Ryegrass	1 1 1	40 lb. 40 lb. 40 lb.

Erosion and Sediment Control Schedule

Ingress-Egress
A stone access drive complete with under lying geo-textile fabric (20 feet wide and 50 feet long) for ingress and egress at the site shall be installed. This drive shall be the only entrance and exit to the site.

Silt Fence
A silt fence shall be installed prior to any earthwork activities
at the site in the locations shown on the site plan as well as along the front of any lot that slopes towards the street.

Temporary Seeding
Disturbed areas of the site that are to remain idle for more than twenty one(21) days shall be properly seeded and straw mulched within seven(7) days of completion of intitial grading. Temporary seeding and mulching as a thirty(30) foot strip of the entire front of the lot shall be maintained on the site once initial grading is complete.

Stabilization of critical areas within fifty(50) feet of any stream or wetland shall be complete within two(2) days of the disturbance if the site is to remain inactive for longer than fourteen(14) days.

Mulchina
Straw—mulch shall be applied at a rate of 1 bale per every ten
(10) feet of curb, at a width of thirty(30) feet to the entire
length of the lot. Wood chips may also be used but must be
spread at a minimum depth of four inches over the thirty—foot
width and must be accompanied by a properly installed silt fence.

<u>Maintenance</u>

Erosion and sediment controls shall be inspected every seven(7) days or within 24 hours of a 0.5" or greater rainfall event. Necessary repairs shall be made at this time.

> "I, the undersigned hereby certify that this topography indicated by 6", 1', or 2' contours, and elevations shown hereon represent an actual field survey made by me on the day of Aug ,20 06 and that the elevations were taken at appropriate intervals and that as of that date they existed as indicated hereon."

Concorn T	WD. LA	VII.	COLIN	iTV OL				
				iii, Or	טור			
for: MUT PANUSIN CUSTOM HOMES								
ADDRESS	\$11	ख्य	СПҮ		72			
	RUE SOUTE	<i>t</i>						
SUBDIVISION 49-24	NAME	— TRACI		SIREET				
SUBLOT NO.	MUDD BOSH	VOL	F6.	PENA PA	CEL NO.			
LEGEND								
SANITARY MANHOLE	0	EXET. ELEV.	1888ء ۔	<u> </u>	ELEV.			
STORM MANHOLE	•	AS BUILT EL	EVATION					
INLET OR CATCH BASIN — HYDRANT —————		کے	NDICATES					
EXISTING CONTOURS		\geq	DIRECTION (SUBSTACE D					
PROPOSED CONTOURS -	05144	<u>V</u>						
REMARKS ALL BOUNDARY DATA SHOWN WAS OBTAINED FROM (DEEDS, RECORDED								
SUBDIVISION PLAT OR OTHER PUBLIC RECORDS)								
LOCATIONS AS SHOWN OF ADJACENT WELLS AND SEPTIC TANKS OBTAINED FROM LAKE COUNTY HEALTH DEPARTMENT								
			A 571 (2) N 1	·				
	ESIGN CE			OPPECT				
TO THE BEST	AS PREPARED OF MY KNOW	VLEDGE A	ND BELIE	玉.	j			
- Jack		VEYOR	634-	MATION NO.				
	CHECK							
NO, OF BEDROOMS DIMENSIONS BEARINGS			SIZE, LOCA	TION				
TIE TO NEAREST STREET		SANL MIL C	MET. ELEV. II	ev. elev.				
SUBLOT NO. PARCEL NO. SURROUNDING OWNERS		SANL COMM. STORM SEW STORM MH.	ER SIZE X C	R. LOC.				
BLDG. DIMENSIONS FIN OR. BLDG. THES FL'R. GRADES		PAN'T TYPE	OPADE CUR XC. SIZE PR	BS EBSURE				
APRON TYPE WOTH THICKN SIDEWALK TYPE WOTH THIC CLAYERT TYPE DA., LENGTH	ICIESS	METT FOCK	K LOCATION NON	& DUPLICAT	ion area			
CULVERT TYPE DIA., LENGTH ROCK OUTCROPPINGS	-	ISOLATION R	POUS FROM	I WELL				
REVISIONS NO. DATE BY	64	PLAN P	REPARED B	Yt				
1	BABCOC	K · JONE	S & AS	SOCIATE	S, INC.			
2		PAINE	DMILLE, CHIO					
3	MANN BY	SCALE		PHONE NO. 440-	367-1811			
•	SHK 0	DATE	777 00	DISAMING NO.				
	CHEN.	APP'0'		04-275	- 20			

REDISTERED SURVEYOR

REG. NO.

EXISTING UTILITIES NOTE:
THE SIZE AND LOCATION, BOTH HORIZONTAL AND VERTICAL
OF THE UNDERGROUND UTILITIES SHOWN HEREON, HAVE BEEN
OBTAINED BY A SEARCH OF AVAILABLE RECORDS.
VERIFICATION BY FIELD OBSERVATION HAS BEEN CONDUCTED
WHERE PRACTICAL, HOWEVER, BABCOCK, JONES AND ASSOCIATES
INC. DOES NOT GUARANTEE THE COMPLETENESS NOR ACCURACY
THEREOF.

