

NOTES

1. ~~PROPOSED~~ EXISTING GROUND GRADES
2. ~~OVERLAND~~ OVERLAND DRAINAGE FLOW
3. BENCH MARK TOP OF LAND ADJUT OF SUBLOT NO. 18 ELEV 592.91
4. --- 590 --- EXISTING CONTOURS
5. --- 590 --- PROPOSED CONTOURS
6. • I.P.S. = 5/8" IRON PIN SET WITH CAP.
7. ROOF DRAINS SHALL DISCHARGE TO SLASH BLOCKS. *Note: Run drains down road to yard drains*
8. SUMP PUMP TO BE INSTALLED FOR FOOTER DRAINS

9. CONTACT O.U.P.S. TWO WORKING DAYS BEFORE DIGGING 1-800-362-2764

I CERTIFY THAT THE BOUNDARY SURVEY IS IN ACCORDANCE WITH CURRENT MINIMUM STANDARDS FOR BOUNDARY SURVEYS IN THE STATE OF OHIO *Ralph W. Kempke P.S. 8257*

I HEREBY CERTIFY THAT ACTUAL FIELD OBSERVATION OF ELEVATIONS HAVE BEEN MADE BY ME ON DECEMBER 4, 2002. THE CIRCLED GRADES ACCURATELY DEPICT THE AS-BUILT CONDITIONS OBSERVED BY ME ON *Ralph W. Kempke P.S. 8257*

FINISH FLOOR GRADES

GARAGE FLOOR 592.78
1ST FLOOR 595.03
BASEMENT FLOOR 586.36
BOTTOM OF FOOTER 585.36

SIL 19
VACANT LOT
FGA 592.2

SIL 20
EX FGA
591.7

