





Seeding Dates	Species	Lb./1,000 ft. <sup>2</sup>	Per Ac.
March 1 to August 15	Oats Yall Fescus Annual Ryegrass	3 · 1 1	4 bushet 40 lb. 40 lb.
	Perennial Ryegrass Tall Fescue Annual Ryegrass	1 1 1	40 lb. 40 lb. 40 lb.
August 16 ta November 1	Rye Tali Fescue Annual Ryegrass	3 1 1	2 bushel 40 lb. 40 lb.
	Wheat Tall Fescue Annual Ryegrass	3 1 1	2 bushel 40 lb. 40 lb.
	Perennial Ryegrass Tall Fescue Annual Ryegrass	1 1	40 lb. 40 lb. 40 lb.

Erosion and Sediment Control Schedule

Ingress-Egress

A stone access drive complete with under lying geo-textile fabric (20 feet wide and 50 feet long) for ingress and egress at the site shall be installed. This drive shall be the only entrance and exit to the site.

Silt Fence

A silt fence shall be installed prior to any earthwork activities at the site in the locations shown on the site plan as well as along the front of any lot that slopes towards the street.

Temporary Seeding
Disturbed areas of the site that are to remain idle for more than twenty one(21) days shall be properly seeded and straw mulched within seven(7) days of completion of intitial grading.

Temporary seeding and mulching as a thirty(30) foot strip of the entire front of the lot shall be maintained on the site once initial grading is complete.

Stabilization of critical areas within fifty(50) feet of any stream or wetland shall be complete within two(2) days of the disturbance if the site is to remain inactive for longer than fourteen(14) days.

Mulching
Straw-mulch shall be applied at a rate of 1 bale per every ten (10) feet of curb, at a width of thirty(30) feet to the entire length of the lot. Wood chips may also be used but must be spread at a minimum depth of four inches over the thirty-foot width and must be accompanied by a properly installed silt fence.

Erosion and sediment controls shall be inspected every seven(7) days or within 24 hours of a 0.5" or greater rainfall event. Necessary repairs shall be made at this time.

> "I, the undersigned hereby certify that this topography indicated by 6", 1', or 2' contours, and elevations shown hereon represent an actual field survey made by me on the 1872 day of 007,2006 and that the elevations were taken at appropriate intervals and that as of that date they existed as indicated hereon."

2								
	PAINESULL	E Tup.		COUNTY	, OHIO			
	for: LILSHIRE HOMES							
	ADDRESS	SII	EET	CITY	ZIP			
I	LAKE ERIE	SHORES 4	TINCT	<del></del>				
	270 VOL-	Pa. Outruege		STR	खा			
	SUBLOT NO.	STREET	VOL-F	Q. PER	A. PANCEL NO.			
	LEGEND  SANTARY MANHOLE							
I	SANITARY MANHOLE	<b>0</b>			PROP. ELEV.			
Ì	INLET OR CATCH BASIN		AS BUILT ELEV	ATION DICATES	Cierr			
ı	EXISTING CONTOURS —	<b>O</b>		RECTION OF				
	PROPOSED CONTOURS—		<b>→</b> \$4	RFACE DRAINAG	£			
	REMARKS ALL BOUNDARY DATA SHOWN WAS OBTAINED FROM (DEEDS, RECORDED							
ı	SUBDIVISION PLAT OF							
	LOCATIONS AS SHOW LAKE COUNTY HEALT	H DEPARTMENT	ELLS AND SEF	TIC TANKS OF	TAINED FROM			
		DESIGN CE						
Ī	THIS PLAT/ TO THE BE	WAS PREPARED STOF MY KNOW	BY ME, AN LEDGE AND	D IS CORRE BELIEF.	CT			
	110	MA M	12 19	0343				
ŀ	NAME: V	CHECK	LICT	REGISTRATION	NO.			
ļ	NO. OF BEDROOMS DIMENSIONS	CNECK	WATER MAIN SI	ZE, LOCATION				
l	BEARINGS TIE TO NEAREST STREET		SAN. SEWER SI SAN. MH. CAST	. ELEV. INV. ELE	<b>v.</b>			
	SUBLOT NO. PARCEL NO. SURROUNDING DIMERS BLDG. DIMENSIONS FIN GI		STORM SEVER	ZE, LOC. DEPTH SIZE X OR. LOC ST ELEV. INV. EL	Ev.			
	BLDG. TIES FL'R. GNADES APRON TYPE WEIGH THICK	MESS	PAY'T TYPE OR GAS LINE LOC.	NDE CURBS SIZE PRESSURE				
	SIDEMALK TYPE WIDTH TH CULVERT TYPE DIA., LENG ROCK OUTCROPPINGS	ICKNESS	WELL LOCATION	ocation & Dup I IUS From Well	LICATION AREA			
ŀ	REVISIONS							
	NO. DATE BY	61 24222	PLAN PREF		4555			
-	1	BABCOCI		& ASSOCI	4/ <i>ES, INC</i> .			
ŀ	3	DRAWN BY	PAINESML	PHONE				
ŀ	4	CHCD.	DATE 10/24		140-357-1811 3 NO.			
ľ	8	CHEF	APPO /		228-270			

"AS BUILT" CERTIFICATION
, HEREBY CERTIFY THAT THE CIRCLED GRADES ARE EXISTING FINISH GRADES CHECKED IN THE FIELD ON. AND ARE CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

REDISTERED SURVEYOR

REG. NO.

EXISTING UTILITIES NOTE:
THE SIZE AND LOCATION, BOTH HORIZONTAL AND VERTICAL
OF THE UNDERGROUND UTILITIES SHOWN HEREON, HAVE BEEN
OBTAINED BY A SEARCH OF AVAILABLE RECORDS. VERIFICATION BY FIELD OBSERVATION HAS BEEN CONDUCTED WHERE PRACTICAL HOWEVER, BABCOCK, JONES AND ASSOCIATES INC. DOES NOT GUARANTEE THE COMPLETENESS NOR ACCURACY THEREOF.

