





Seeding Dates	Species	Lb./1,000 ft. ²	Per Ac.
March 1 to August 15	Oats Tall Feacus Annual Ryagrasa	3 · 1 1	4 bushet 40 lb. 40 lb.
	Perennial Ryegrass Tall Fescus Annual Ryegrass	1 1 1	40 lb. 40 lb. 40 lb.
August 16 to November 1	Rye Tali Fescue Annual Ryegrass	3 1 1	2 bushel 40 lb. 40 lb. 2 bushel 40 lb. 40 lb.
	Wheat Tall Fescue Annual Ryegrass	3 1 1	
	Perennial Ryegrass Tall Fescue Annual Ryegrass	1 1 1	40 lb. 40 lb. 40 lb.

Erosion and Sediment Control Schedule

Ingress—Egress
A stone access drive complete with under lying geo—textile fabric (20 feet wide and 50 feet long) for ingress and egress at the site shall be installed. This drive shall be the only entrance and exit to the site.

Sit Fence
A silt fence shall be installed prior to any earthwork activities at the site in the locations shown on the site plan as well as along the front of any lot that slopes towards the street.

Temporary Seeding.
Disturbed areas of the site that are to remain idle for more than twenty one(21) days shall be properly seeded and straw mulched within seven(7) days of completion of intitial grading.
Temporary seeding and mulching as a thirty(30) foot strip of the entire front of the lot shall be maintained on the site once initial grading is complete.

Stabilization of critical areas within fifty(50) feet of any stream or wetland shall be complete within two(2) days of the disturbance if the site is to remain inactive for longer than fourteen(14) days.

Mulching.
Straw—mulch shall be applied at a rate of 1 bale per every ten (10) feet of curb, at a width of thirty(30) feet to the entire length of the lot. Wood chips may also be used but must be spread at a minimum depth of four inches over the thirty—foot width and must be accompanied by a properly installed silt

<u>Maintenance</u>

Erosion and sediment controls shall be inspected every seven(7) days or within 24 hours of a 0.5" or greater rainfail event.

Necessary repairs shall be made at this time.

"I, the undersigned hereby certify that
this topography indicated by 6", 1', or 2'
contours, and elevations shown hereon
represent an actual field survey made by me on the 2014 day of ANUL, 2007
and that the elevations were taken at
appropriate intervals and that as of that date they existed as indicated hereon."
aute they existed as indicated hereon.

' '	ve Twile	· /	_ COUN	NTY, OHIO
for: Will	SHIPE +	tomes	OWNER	
ACORESS		TREET	CITY	219
LAKE ERLES	SHOLES 44			
SUBOMISION 50-	33 NAME	······································		SINEEL
SUBLOT NO.	OVTLIGGE	VOL	-Fa.	PENM. PANCEL NO
	LEG	END		
SANTARY MANHOLE	0	DOST. ELEV	-2=1 888	#2 PROP. ELEV.
STORM MANHOLE	Š	AS BUILT E	LEWATION	(60)
INLET OR CATCH BASIN -		احر ا	INDICATES	A CS
EXISTING CONTOURS -		>	DIRECTION (
PROPOSED CONTOURS—		_ ▽	SUITALE, D.	
		ARKS	. (DEEDe 1	MCCCOCCED
ALL BOUNDARY DATA SUBDIVISION PLAT OF	ROTHER PUBLIC	RECORDS)	i (DEEDS, I	RECORDED
LOCATIONS AS SHOW LAKE COUNTY HEALTI	N OF ADJACENT 1 H DEPARTMENT	WELLS AND S	BEPTIC TAN	KS OBTAINED FRO
	DESIGN C	ERTIFIC	ATION	
THIS PLAT	WAS PREPARE	D BY ME.	AND IS C	ORRECT
1 1	INA A	MLEUGE A WAL	W_34	き
NAME V		NYEY CH	NEW S	NATION NO.
W	CHEC	K LIST		
NO. OF BEDROOMS DIMENSIONS BEARINGS		SAN, SEWE	N SIZE, LOCA R SIZE X GR	LOC.
I TIE TO NEAREST STREET		SAN. MH. C	MET. ELEV. II . SKZE, LOC. MER SKZE X (W. ELEV. DEPTH
SUBLOT NO. PARCEL, NO. SURROUNDING OWNERS BLDG, DMENSIONS FIN OF		E STORM MH.	CAST ELEV.	NV. ELEV.
BLDG. TIES FL'R. GRADES APRON TYPE WORN THOM	OFER	I CAS LINE L	00. SZZ PRI	ESSURE & DUPLICATION ARE
SIDEMALK TYPE WIDTH TH CULVERT TYPE DIA., LENG ROCK OUTCROPPINGS	ILH LH	METT FOCK	TION RADIUS FROM	
REVISIONS	1			
NO. DATE BY	164		REPARED B	
1	BABCO			SOCIATES, INC
2	DRAWN BY	PAINE	SWITE OHO	PHONE NO.
3	CHKTD.	DATE		440-357-18 MANUSIC NO.
4	CIEW	APP TO		05-228-26
5	CHEF		147	0) 100 00
"AC 1	BUILT" CERT	IFICATION	ı	

I, HEREBY CERTIFY THAT THE CIRCLED GRADES ARE EXISTING FINISH GRADES CHECKED IN THE FIELD ON _______, 20_____ AND ARE CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

REDISTERED SURVEYOR

REG. NO.

EXISTING UTILITIES NOTE:
THE SIZE AND LOCATION, BOTH HORIZONTAL AND VERTICAL
OF THE UNDERGROUND UTILITIES SHOWN HEREON, HAVE BEEN
OBTAINED BY A SEARCH OF AVAILABLE RECORDS.
VERIFICATION BY FIELD OBSERVATION HAS BEEN CONDUCTED
WHERE PRACTICAL, HOWEVER, BABCOCK, JONES AND ASSOCIATES
INC. DOES NOT GUARANTEE THE COMPLETENESS NOR ACCURACY
THEREOF.

