




Willard F. Schade
11/04/09

SCHADE SURVEYING COMPANY
4043 Erie Street
Willoughby, Ohio 44094
440-951-6454

Lot Split Survey for Tompkins
7115 Farnham Drive
Mentor, Ohio
Subdivision of Sublot 141
of the Mentor Estates Subdivision
as recorded in Volume H of Maps,
Pages 1-5 Lake County Records
Bases of bearings are the north
margin of Farnham Drive being
North 90 degrees 00' 00" East
as shown by said Plat
File No. 09-1880
Field Book 130, Page 25
Drawing Name Farnham.Zak
November 4, 2009

