## **CERTIFICATION:** This survey is made for the benefit of: Willoughby Tramz, LLC; Motel 6 Operating L.P., and Chicago Title Insurance Company. CHICAGO TITLE INSURANCE COMPANY CHICAGO TITLE INSURANCE COMPANY **MISCELLANEOUS NOTES:** COMMITMENT NO. 28330213 - SCHEDULE B. SECTION II: **COMMITMENT NO. 28330213 - SCHEDULE A:** 1. There is direct access to the subject property via Maplegrove Road, a public right-of-way. Numbers correspond with Schedule B exception items contained in the above referenced Title Situated in the City of Willoughby and City of Willoughby Hills, County of Lake, and State of Ohio: and 2. The current zoning classification allows for the subject property to be used as a Hotel. known as being a part of original Willoughby Township Lot No. 3, Tract No. 6 and being bounded and Commitment. Legal Description: 3. The locations of utilities shown on the survey are from visible evidence, markings by others and plans described as follows: 1. Note: Premises under examination abut on interstate Highway 90, a limited access interstate highway, provided by others. 4. The posted address on site is 35110 Maplegrove Road. to which vehicular access from abutting property is denied between regularly constituted access points. Beginning in the centerline of Hanno Road, now vacated 60 feet wide, at its intersection with the 5. At the time of this survey there was no observable surface evidence of earth moving work, building Southerly sideline of Maplegrove Road, width varies, said point lying South 1713'00" East along said (MAY AFFECT THE SUBJECT PROPERTY - NO DOCUMENTS SPECIFIED / DOCUMENT NOT PROVIDED) construction or building additions within recent months. centerline, a distance of 39.89 feet from a spike set at its intersection with the centerline of 6.At the time of this survey, there was no observable evidence of the subject property being used as a Maplegrove Road; Thence South 17"13"00" East, along said centerline of Hanna Road, (now vacated), a 2. "INTENTIONALLY DELETED" solid waste dump, sump or sanitary landfill. distance of 380.81 feet to an iron pin set at an angle point therein; Thence South 23'06'00" East (Vacated per Plat Volume 12, Page 833); 7. At the time of this survey, there was no observable evidence of any recent changes in street continuing along said centerline, a distance of 31.75 feet to an iron pin set at its intersection with the 3. Easement as contained in Instrument Recorded in Volume 495, Page 833 of Lake County Records. right-of-way lines either completed or proposed, and available from the controlling jurisdiction. Thence, South 17"13"00" East along the centerline of said vacated Hanna Road, a distance of 39.89 feet to an "x-cut" found in concrete at the Northwest corner of land now or formerly conveyed to DMD Realty, LLC, as recorded in Document No. 2004R036998 of the Lake County Records, said point also being the POINT OF BEGINNING: (AFFECTS THE SUBJECT PROPERTY - PLOTTED AND SHOWN HEREON) Northerly limited access line of Interstate Route 90: thence North 59\*44'40" East, along said Northerly 8. At the time of this survey, there was no observable evidence of any recent street or sidewalk limited access line, passing an iron pin set at 30.24 feet, a total distance of 522.42 feet to an iron pin set at its intersection with said Southerly sideline of Maplegrove Road; Thence North 61'58'19" West 4. The vacation Plat of Hanna Road as Recorded in Plat Volume 12, Page 40 shows the following: The 9. The Property surveyed and shown hereon is the same property described in Schedule A of Chicago along said Southerly sideline, a distance of 179.35 feet to an iron pin set at an angle point therein; vacated portion of Hanna Road is subject to a drainage, sanitary sewer, waterline and utility easement." Title Commitment No. 28330213 with an effective date of February 21, 2008. (AFFECTS THE SUBJECT PROPERTY - PLOTTED AND SHOWN HEREON) Thence North 85'33'25" West along said Southerly sideline, a distance of 260.00 feet to an iron pin set an angle point therein; Thence North 78'30'14" West, continuing along said Southerly sideline, a distance 5368" found at an angle point in the east line of said land of LAGS Associtates - Fast LLC: of 130.30 feet to an iron pin set at an angle point therein at its intersection with the Easterly sideline of said Hanna Road, now vacated; Thence South 88'47'29" West, continuing along said Southerly sideline Thence, South 23'06'00" East continuing along said centerline and east line of said land of LAGF Associtates — East, LLC, a distance of 31.75 feet to a 5/8" capped rebor set **BASIS OF BEARING:** of Maplegrove Road, a distance of 31.21 feet to the place of beginning. point also being on the North line of Interstate Highway 90 (Variable Width - Limited Access); The meridian for all bearings shown hereon is the Westerly property line of subject property also being the centerline of former Hanna Road known as being South 17"13"00" East per Lake County Record. PARKING: **ENCROACHMENTS:** aforementioned Maplegrove Road; 2' Parking Encroachment over Parking setback. 130 Parking Spaces Thence, North 61°58'19" West along to south line of Maplegrove Road, a distance of 179.35 feet to a 5/8" capped rebar stamped "6832" found at an angle point; 8' Parking Encroachment over Parking setback. 14' Parking Encroachment over Parking setback Willoughby an approximate distance of 30.62 feet to a 5/8" capped rebar stamped "LDC 5368" found at an angle point; D 9' Parking Encroachment over Parking setback. Thence, North 78'30'14" West continuing along said south right of way line, a distance of 130.30 feet to a PK nail set at an angle point; Thence, South 88'47'29" West continuing along said south right of way line, a distance of 31.21 feet to the POINT OF BEGINNING; 2' Building Encroachment over Building setback. **FLOOD ZONE:** By scaled map location and graphic plotting only, the subject property appears to lie entirely in Zone C (Areas of minimal flooding) according to the Flood Insurance P.O.R. - Title Rate Map for the County of Lake, Community Panel No. 3903220006A, Effective Date January 16, 1981. 1P.O.C. — Surveyor's Legal Railroad Spike Found & Used February 21, 2008. **ZONING:** All rebar set are 5/8 inch in diameter, 30 inches in length with a yellow, plastic stamped "MILLMAN 330-342-0723". Zoning Classification: G-B (General Business) I further certify that: Maplegrove Road "X" Notch in Concrete Maximum Building Height: 60' Found & Used — Building Setbacks: Front=40', Side=10' (west property line), Side=40' (east Variable Width Public Right of Way property line), Rear=10' (Asphalt Pavement) 2. That there are no visible encroachments on the subject property or upon adjacent land abutting said property except as shown hereon; Parking Setbacks: Front=20', Side=5' (west property line), Side=15' (east property 7 31.21' 3. That the title lines and the lines of actual possession are the same and the improvements erected on the property as shown hereon do not encroach over the property lines, line), Rear=5' Dd. & Used -5/8" Capped Reb lots lines, building lines, setback lines, title lines, government lease or patent lines or over any easement or rights of way, P.O.B. - Title Parking Ratio: 1 Space per guest room or suite, plus 1 space per every 2 (N 78°30'14" W 130 30' P.O.B. — Surveyor's Legal 4. All courses and distances and other measurements were established by actual field measures and the boundaries and monuments indicated hereon were actually located; \_"LDC 5368" Note: Buildings with a height greater than 35' shall provide an additional 10' of Dd. & Used) side and rear yard setbacks for every 12' of building height greater than 35' shows the point of entry and location of any utilities which pass through or are located on adjoining private land. P (N 85°33'25" W 260.00' Dd. & Msd.) Zoning information provided by the City of Willoughby, phone: (440) 953-4207 764.51 6. All applicable setback and sideyard lines are shown on the survey and there are no violations of any applicable zoning or subdivision ordinances; 9' Parking Encroachment Found & Used 7. This map or plat and the survey on which it is based were made (i) in accordance with the "minimum standard detail requirements for ALTA/ACSM Land Title Surveys," jointly ±30.62 764.90 from the survey measurements made on the survey do not exceed the allowable positional tolerance. 14' Parkina Encroachment \_★764.51 **₩**764.94 over Porking Setback 764.70 12 0 HC over Parking Setback or otherwise noted as to their effect on the subject property. over Building Setback 20' Height Concrete 9. Said described property is located within an area having a zone designation C by the Federal Emergency Management Agency (FEMA), on flood insurance rate map no. 0006A, with a date of identification of January 16, 1981, for Community No. 390322, in the City of Willoughby and City of Willoughby Hills, State of Ohio, which is the current flood insurance map for the community in which the said premises is situated. ~Asphalt~ 10. The property has direct access to Maplegrove Road, a dedicated public street. NOW OR FORMERLY: **★**764.92 764.99 DMD REALTY, LLC Field work completed February 29, 2008. TIMOTHY DOCUMENT #2004R036998 PARCEL #27A-001-00-055 FINKE 111 S-8392 Vested In: C'STERED. Willoughby Tramz, LLC Deed Book 1059, Page 547 Parcel No. 27A-001-00-024 & 31A-012-00-005 Ohio Professional Surveyor No. 8392 For and on behalf of Millman Surveying, Inc. 5/8" Capped Rebar Found & Used "6832" Date of Survey: February 29, 2008 Total Land Area: City of Willoughby: ±97,220 Square Feet ±2.2319 Acres Village of Willoughby Hills: ±21,324 Square Feet ±0.4895 Acres Total Land Area: 118,544 Square Feet 2.7214 Acres 765.24 **ALTA/ACSM LAND TITLE SURVEY GRAPHIC SCALE** PREPARED FOR: ····3 Story··· ·· Brick Building · 13,837 Sq. Ft in Plat Volume 12, Page 83 1 INCH = 30 FT.36' Height. **NORTH** 5/8" Capped Rebar\_ Found On-Line "LDC 5368" **Accor North America** SYMBOL LEGEND 4001 International Parkway Carrollton, TX 75007 Phone: (972) 360-2716 - Fire Hydrant R/W Right-of-Way - Adjoiner Property Line Water Valve - Centerline - Water Manhole - Place/Point of Beginning - Sanitary Manhole - Place/Point of Reference Fairfield Inn - Air Condition Unit - Encroachment/Protrusion - Utility Pedestal (As Noted) 35110 Maplegrove Road Schedule B-Section II Item $\times$ - Electric Transforme **City of Willoughby** Calc. - Calculated Volume 495, Page 833 - Bollard Post - Measured - Handicap Space **County of Lake** - Deed 👓 – Sign NOW OR FORMERLY: \\ LAGF ASSOCIATES — EAST, LLC - Finished Floor Elevation **UTILITY INFORMATION State of Ohio** - Drainage Flow Direction - Utility Pole DOCUMENT #980058969 SANITARY Lake County Water 105 Main St Painsville, OH 44077 - Ground Shot Elevation (GS) ELECTRIC Illuminating Company 76 South Main St PARCEL #27A-001-00-025 - Light Pole - Monumentation Found as Noted (Use - Vacant) — → Guy Wire - Railroad Spike Found Drawn By: MRK O Guardrail Akron, OH 44308 - 5/8" Rebar w/Cap Set — □ — - Fence (As Noted) (440) 350-2645 (800) 589-3101 Scale: 1"=30' Date: February 29, 2008 "MILLMAN 330-342-0723" —san— - Sanitary Sewer WATER Lake County Water TELEPHONE SBC - AT&T - P.K. Nail or Drill Hole Set —stm— – Storm Sewer Sheet: 1 of 1 Checked: TAF Maplegrove Rd - No. of Regular Parking Spaces 105 Main St 45 Erie View Plaza 5/8" Copped Rebar Found & Used

Painsville, OH 44077

(440) 350-2645

1201 E 55th St

(800) 362-7557

Cleveland, OH 44103-1028

UNDERGROUND UTILITIES

NON-MEMBERS MUST BE CALLED DIRECTLY

BEFORE YOU DIG
CALL1-800-362-2764 (TOLL FREE)
TITY NOTIFICATION CENTER OF OUT

"L.D.C. INC. 5368"

5/8" Capped Rebar Found

S61'50'44"W 3.38' from —

comer "SHA 5108"

Cleveland, OH 44114

(800) 288-2020

77 N St Clair St

(877) 772–2253

Painsville, OH 44077

**VICINITY MAP** NOT TO SCALE

CABLE T.V. Time Warner

Project Manager: DLH **REVISION NOTES** Date: | Comment: 17/08 Utility Update, Legal Description, Zoning, Cert. /21/08 Legend Symbol—Iron to P.K. Nail 3/25/08 Added gas line IK 4/03/08 Surveyor's Legal Description Added

TING, Inc.

ΛE

SUR

National Commercial Division

I, Timothy A. Finke, PS a Registered Land Surveyor do hereby certify to the aforesaid parties as of the date set forth that I have made a survey of a tract of land described as

A certain parcel of land situated in the City of Willoughby and the Village of Willoughby Hills, County of Lake, State of Ohio. Known as being a part of the original Willoughby Township Lot No. 3, Treet No. 6. Known as being a portion of The Vacated Plat of Hanna Road, as recorded in Plat Volume 12, Page 833 of the Lake County Records. Known as being all of land now or formerly conveyed to Willoughby Tramz, LLC, as recorded in Deed Book 1059, Page 547 of the Lake County Records and being more particularly

COMMENCING at a railroad spike found at the intersection of the centerline of Maplegrove Road (Variable Width - Public) with the centerline of Hanna Road (60' Wide - Public)

Thence, South 17"13"00" East continuing along the centerline of said Hanna Road and the east line of said land of DMD Realty, LLC and also the east line of land now or formerly conveyed to LAGF Associates — East, LLC, as recorded in Document No. 980058969 of the Lake County Records, passing a 5/8" capped rebar stamped "LDC 5368" found at the Southeast corner of said land of DMD Realty, LLC, at a distance of 209.83 feet, for a total distance of 380.81 feet to a 5/8" capped rebar stamped 'LD.C. Inc.

at the Southeast corner of said land of LAGF Associates — East, LLC, reference a 5/8" copped rebar stamped "SHA 5108" found South 61"50"44" West from said corner, said

Thence, North 59'44'40" East along the north line of said Interstate Highway 90, passing over the corporate division line between the City of Willoughby and the Village of Willoughby Hills at an approximate distance of 284.47 feet, for a total distance of 522.42 feet to a 5/8" capped rebar stamped "6832" found on the south line of

Thence, North 85'33'25" West continuing along the south right of way line, passing over the corporate division line between the Village of Willoughby Hills and the City of

Containing 118,544 square feet (2.7214 acres) of land, more or less, approximately 97,220 square feet (2.2319 acres) of which lies within the City of Willoughby and approximately 21,324 square feet (0.4895 acres) of which lies within the Village of Willoughby Hills, as surveyed in February of 2008 by Timothy A. Finke, PS, Ohio Registered Professional Licensed Surveyor No. S-8392 for and on behalf of Millman Surveying, Inc. and is subject to all legal highways and easements of record.

The basis of all bearings shown hereon is the west line of the subject property known as being South 1773'00" East per Deed Book 1059, Page 547 of the Lake County Records.

The above described percel of land is all of the same land as described in Chicago Title Insurance Company Title Commitment No. 028330213, having an effective date of

- 1. The accompanying survey was made on the ground and correctly shows the location of all buildings, structures and other improvements situated on the above premises;

- 5. All utility services required for the operation of the property and the improvements thereon either enter the property through the adjoining public streets and/or the survey
- established and adopted by ALTA, ACSM and NSPS in 2005, and includes item 1-4, 6, 7(a), 7(b), 8-10, 11(b) and 13, 14, 16-18 of table "a" thereof, and (ii) pursuant to the accuracy standards as adopted by ALTA, NSPS and ACSM in effect on the date of this certification, the undersigned further certifies that the positional uncertainties resulting
- 8. The property described hereon is the same property described in Chicago Title Insurance Company Commitment No. 28330213 dated February 21, 2008, and that all easements, covenants and restrictions referenced in said title commitment are apparent from a physical inspection of the site otherwise known to me have been platted hereon

 No. of Handicap Parking Spaces Storm Manhole - Catch Basin Cleanout

- Electric Meter

Gas Meter

- Water Stand Pipe

——g—— — Underground Gas

-ou- - Overhead Utilities

- Concrete Area - No Parking Area - Building Area

MSI Site No.: 13364