

S.R. 2 & U.S.R. 20 INTERCHANGE

SOIL PROFILE
LAKE COUNTY
LAK-2-16.49
OHIO STATE HIGHWAY
TESTING LABORATORY
COLUMBUS, OHIO

| CROSS SECTION INDEX | |
|---------------------|-------|
| Station | Sheet |
| 862+00 | 22 |
| 863+00 | 23 |
| 864+00 | 23 |
| 865+00 | 23 |
| 866+00 | 23 |
| 868+00 | 24 |
| U.S.R. 20 | |
| 116+25 | 10 |

| INTERCHANGE INDEX | |
|----------------------------|-------|
| Profile | Sheet |
| Survey Centerline S.R. 2 | |
| Sta. 862+00 to Sta. 872+00 | 9 |
| Sta. 872+00 to Sta. 884+00 | 10 |
| Westbound Lanes | 9 |
| Eastbound Lanes | 10 |
| U.S.R. 20 | 10 |
| Ramp N-N | 9 |

