

REF. NO.	STATION		SIDE	ROADWAY																			
				202	202	202	202	202	202	202	202	608	830										
				WALK REMOVED	PIPE REMOVED, 24" AND UNDER	MANHOLE REMOVED	CATCH BASIN REMOVED	REMOVAL MISCELLANEOUS: LANDSCALE GARDEN	REMOVAL MISCELLANEOUS: SIGN	REMOVAL MISCELLANEOUS: LAMP POLE		4" CONCRETE WALK		CURB, TYPE 6									
FROM	TO		SQ. FT.	LIN. FT.	EACH	EACH	EACH	EACH	EACH		SQ. FT.		LIN.FT.										
R-1	407+90.66	407+93.07	LT.		5	1	1																
R-2	410+06.84	410+13.22	LT.		5	1	1																
R-3	407+93.07	-	RT.				1																
R-4	407+00.00	411+00.00	RT.	1728																			
R-5	409+60.00	-	LT.					1															
R-6	408+95.00	-	RT.						1														
R-7	409+05.00	-	RT.							1													
SW-1	407+00.00	409+15.00	RT.									1183											
SW-2	409+30.00	409+60.00	RT.									180											
SW-3	409+76.00	411+00.00	RT.									744											
C-1	407+00.00	409+15.00	RT.											215									
TOTALS CARRIED TO ROADWAY SUB-SUMMARY				1728	10	2	3	1	1	1		2107		215									

REF. NO.	STATION		SIDE	DRAINAGE & EROSION CONTROL																			
				603	604	604																	
				15" CONDUIT, TYPE B	MANHOLE, NO. 3 AS PER PLAN	CATCH BASIN, NO. 3A																	
FROM	TO		LIN. FT.	EACH	EACH																		
D-1	407+00.00	407+93.00	LT.	93	1																		
D-2	407+93.00	-	LT.	5		1																	
D-3	407+93.00	410+14.00	LT.	221		1																	
D-4	407+93.00	-	LT. & RT.	54		1																	
D-5	410+14.00	-	LT. & RT.	53		1																	
TOTALS CARRIED TO DRAINAGE SUB-SUMMARY				426		1	4																