

RECORD OF SURVEYS,

Plat of *Survey*, No. *144*, *Seroy* Township, Range

Survey made *July 29* ¹⁹⁰⁵/₁₈₉ at the request of *Trustees of Seroy Township*
 For the purpose of *altering line of road*

by _____ County Surveyor.

DESCRIPTION.

Plat of road in lots 19 and 9 Seroy Township, Lake Co. Ohio showing alterations necessary to repair washouts caused by Grand River at the line between lot 19 and (and by Pine Creek at a point about 700 feet south of said line. The line marked and shown on the plat is the westerly boundary of said highway by a agreement between the Trustees of Seroy Township and the land owners. Pine creek and Grand River to fix the easterly boundary of said highway

CALCULATIONS.

Sta.	Course	Distance.	Latitude.		Departure.		Double Longitude.	Double Areas.		REMARKS
			North.	South.	East.	West.		North.	South	

I, _____ County Surveyor of Lake County, Ohio, do hereby certify, that I have surveyed and subdivided Lot No. *a road* in Tract No. _____ Township of *Seroy* in accordance with the statutes of Ohio, and the laws of the United States. Surveyed pursuant to the application of *Township Trustees* and _____

July 29 1905 A D. 189
J. L. Ward County Surveyor.

} Flagmen.
 }
 } Markers.

} Tapemen.

LAKE COUNTY, OHIO.

