


BEARINGS SHOWN HEREON ARE BASED ON THE OHIO COORDINATE SYSTEM OF 1983 - NORTH ZONE, 1986 ADJUSTMENT.

SURVEYOR CERTIFICATION
 I HEREBY CERTIFY THAT I HAVE SURVEYED THE PREMISES SHOWN HEREON, AND PREPARED THE ATTACHED PLAT IN ACCORDANCE WITH THE PROVISIONS OF CHAPTER 4733-37 OF THE OHIO ADMINISTRATIVE CODE. THE DIMENSIONS SHOWN HEREON ARE IN FEET AND DECIMAL PARTS THEREOF, ALL OF WHICH ARE CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. MONUMENTS AS INDICATED WERE FOUND OR SET AS SHOWN HEREON.

Michael P. Spellacy 10/24/2013
 MICHAEL P. SPELLACY P.S. #8169 OCTOBER 24, 2013 DATE



BOUNDARY SURVEY LEGEND

| | | | |
|---------------------------------------|---|-----------------|-----------------------------------|
| 5/8" X 30" Iron Pin Set (Id. Polaris) | ○ | A, Act. | Actual Measurement or Calculation |
| Iron Pin/Pipe Found | ● | U, Used | Used Measurement or Monument |
| Mon Box Found With Pin/Pipe | M | M, Msd. | Measured |
| Monument Box Found (Empty) | ■ | D, R, Rec. | Deed or Record |
| Survey Nail Set | △ | Calc. | Calculated |
| Survey Nail Found | △ | C/L | Centerline |
| Stone/Concrete Monument Found | ⊙ | O, Obs. | Observed |
| Drill Hole Set | ⊙ | P.P.N. | Permanent Parcel Number |
| Drill Hole Found | ⊙ | | |
| Railroad Spike Set | ⊕ | | |
| Railroad Spike Found | ⊕ | | |


Bent
 1" Axle
 Found
 0.50' North
 0.33' East

1" Axle
 Found/Used

| REV. No. | DATE | BY | CHK'D |
|----------|------|----|-------|
| | | | |
| | | | |
| | | | |
| | | | |

DATE: 10/15/2013
 SCALE: HOR. 1" = 100'
 VERT. 1" = 0'
 FOLDER: Survey
 FILENAME: Plat of Lot Split
 TAB: Map of Lands
 DRAWN: MPS

Map of Lands
 Lot Split
 Concord Township - Lake County - Ohio



POLARIS ENGINEERING & SURVEYING, INC.
 34600 CHARDON ROAD - SUITE D
 WILLOUGHBY HILLS, OHIO 44094
 (440) 944-4433 (440) 944-3722 (Fax)
 www.polaris-es.com

Concord Township

| | |
|--------------|----|
| CONTRACT No. | |
| 13048 | |
| SHEET | OF |
| 01 | 01 |

