

SCHADE SURVEYING COMPANY


Professional Land Surveying
 Northeastern Ohio
 4043 Erie Street
 Willoughby, Ohio 44094

Phone (440) 951-6454
 Fax (440) 951-4496



Willard F. Schade
 6-3-04

Survey for Wenger
 960 Bryn Mawr Avenue
 Wickliffe, Ohio
 File No. 09-1954
 Field Book 129, Page 41
 Drawing Name Wenger.zak



C. P. Gulla #7418
 5/8" i pin found
 at se cor S/L 194
 S & Z Sub. No. 2

100.00'
 record & observed

5/8" iron pin
 found & used

55.00' deed
 & observed

Bryn Mawr Avenue 60'

C. Pomplias
 PPN 29A002G000270
 Volume 1194, Page 204 O. R.

Schade 5/8"
 iron pin set

Jovic Properties
 29A002G000250
 1999R003725

S 17°41'10"E
 56.00' record
 & used

5/8" iron pin
 found & used

211.84' Calc. & obs.

N 72°12'20"E

Robert & Floria Wenger
 PPN 29A002G000260
 Volume 835, Page 1355 O. R.
 0.2692 Acres

Schade 5/8"
 iron pin set

Salante Inc.
 PPN 29A002G000050
 Volume 916,
 Page 829 O. R.

N 22°30'30"W
 56.22' deed
 & used

S 72°12'20"W

206.89' Plat & used

T. & S. Kozlina
 PPN 29A002F010080
 Volume 830, Page 878 O. R.
 Sublot 194
 S & Z Sub.

315.00' Plat & used

Roberta Cirino
 PPN 29A002G000040
 Volume 671,
 Page 924 O. R.

5/8" iron pin
 found & used

5/8" iron pin found at
 se cor. S/L 200 of the
 Schwartz & Zaremsky Inc.
 Subdivision No. 2 as recorded
 in Volume K, Page 79 of
 Lake County Records