THE SHOPPES AT WILLOUGHBY

LOT SPLIT / CONSOLIDATION AND EASEMENTS


PARKING TABULATION AND EXISTING CONDITIONS

INDEX OF SHEETS

TENANT SPACE	AREA	PARKING RATIO	PARKING SPACES
PRODUCE PACKING INC. PROPOSED BUILDING			
SPACERETAIL — AREA 1	12,579 SF	DIVIDED BY 250 SF =	51 CARS
RETAIL — AREA 2	3,883 SF	DIVIDED BY 250 SF =	16 CARS
DISTRIBUTION — AREA 1	24,180 SF	DIVIDED BY 800 SF =	31 CARS
DISTRIBUTION — AREA 2	23,354 SF	DIVIDED BY 800 SF =	30 CARS
DISTRIBUTION — AREA 3	15,400 SF	DIVIDED BY 800 SF =	20 CARS
DISTRIBUTION — AREA 4	14,097 SF	DIVIDED BY 800 SF =	18 CARS
DISTRIBUTION — AREA 5	15,500 SF	DIVIDED BY 800 SF =	20 CARS
DISTRIBUTION — AREA 6	3,332 SF	DIVIDED BY 800 SF =	5 CARS
BUSINESS SERVICES - AREA 1	2,449 SF	DIVIDED BY 300 SF =	9 CARS
BUSINESS SERVICES - AREA 2	2,750 SF	DIVIDED BY 300 SF =	10 CARS
ADMINISTRATIVE - AREA 1	6,733 SF	DIVIDED BY 300 SF =	23 CARS
ADMINISTRATIVE - AREA 2	2,750 SF	DIVIDED BY 300 SF =	10 CARS

TENANT SPACE AREA PARKING SPACES PARKING RATIO GIANT EAGLE - RETAIL 66,044 SF DIVIDED BY 250 SF = 264 CARS COLLEGE 21,856 SF DIVIDED BY 250 SF = 87 CARS UNOCCUPIED DIVIDED BY 250 SF = 53 CARS 13,400 SF UNOCCUPIED 4,033 SF DIVIDED BY 250 SF = 16 CARS CITY BEAUTY - RETAIL 4,227 SF DIVIDED BY 250 SF = 17 CARS DOLLER GENERAL - RETAIL 8,000 SF DIVIDED BY 250 SF = 32 CARS DIVIDED BY 250 SF = 38 CARS UNOCCUPIED - RETAIL 9,511 SF MOVIE THEATER - UNOCCUPIED - RETAIL 35,599 SF DIVIDED BY 250 SF = 142 CARS UNOCCUPIED - RETAIL 24,500 SF DIVIDED BY 250 SF = 98 CARS FITNESS CENETER 30,659 SF DIVIDED BY 200 SF = 153 CARS PRODUCE PACKING INC. SEE TABLE TO LEFT 253 CARS 129,917 SF

TOTAL SHOPPING CENTER SPACES REQUIRED = 1,153 TOTAL SHOPPING CENTER SPACES OBSERVED = 1,663



1 INCH = 80 FEET

HILLS - LOEHMANS PLAZA -27853 EUCLID-CHARDON ROAD

CITY OF WILLOUGHBY HILLS COUNTY OF LAKE - STATE OF OHIO

Source information from plans and markings has been combined with observed evidence of utilities to develop a view of those underground utilities. However, lacking excavation, the exact location of underground features cannot be accurately, completely and reliably depicted. Where additional or more detailed information is required, the client is advised that excavation may be necessary. (OUPS Reference Nos. A831603215-00A, A831603217-00A, A831603255-00A & A831603256-00A)

