

BULK SAMPLE LAB AND CUSTODY DATA

Job Number: LAK-2-3.32
PID 13486

Building: PARCEL 9
36628 VINE STREET
EASTLAKE, OHIO

10/2

SAMPLE NUMBER	SAMPLE DESCRIPTION AND LOCATION	LAB RESULTS
LAK-2-PC9-#1	Acoustic Ceiling Panels - Basement Ceiling	ND
" " #2	PLASTER - Basement Stairway Ceiling	2% chry / .50 PC
" " #3	Plasterboard - Basement Stairway Wall	ND
" " #4	Plasterboard Joint - 1st Flr. S-Office Wall Center	N.D
" " #5	Plasterboard - 1st Flr. Front Office Wall	ND
" " #6	Plasterboard - 1st Flr. Front Office Ceiling	3% chry / .75 PC
" " #7	Plasterboard - 1st Flr. Rear Office - Wall	2% chry / .75 PC
" " #8	Vinyl Flr. Tile - 1st Flr. Front Office Floors	ND
" " #9	Plaster - 2nd Flr. Stairway Wall End Joint	3% chry / .50 PC
" " #10	Vinyl Flooring - 2nd Flr. Stairway Steps	ND
" " #11	Vinyl Flr. Tile - 2nd Flr. Office Floors	3% chry + Mastic
" " #12	Plasterboard - 2nd Flr. Bath Wall	ND
" " #13	Plaster - 2nd Flr. S-Office Wall	2% chry / .25 PC
" " #14	Plaster - 2nd Flr. Hallway Ceiling	2% chry / .50 PC
" " #15	Plasterboard - 2nd Flr. N-Office Wall	2% chry / TRACE

ABBREVIATIONS: ND = Not Detected CHRY = Chrysotile TREN = Tremolite CROC = Crocidolite
 NA = Not Analyzed AMOS = Amosite ACT = Actinolite ANTH = Anthophyllite
 PC = POINT COUNT

SPECIAL NOTES:

SAMPLING BY: LEON BELL Date: 3/7/8

LABORATORY ID#: _____

TRANSPORTED BY: DHL Date: _____

ANALYSIS METHOD: PLM

RECEIVED BY: [Signature] Date: 3/24/08

ANALYZED BY: [Signature] Date: 3/24/08

LEON BELL
 Entry Specialist

2088 South Adington Street
 Akron, Ohio 44306
 330-4891, or 800-468-1130
 Fax 330-786-4879
 Page# 330-914-6046

10/2