

BULK SAMPLE LAB AND CUSTODY DATA

Job Number: LAK-2-3.32
PID-13486

Building: Parcel 9
36628 Vine Street
East Lake, Ohio

2 of 2

SAMPLE NUMBER	SAMPLE DESCRIPTION AND LOCATION	LAB RESULTS
LAK-2-Parcel 9-#16	Plaster Board - 2nd Flr. Rear Office Wall	ND
" - #17	Window Glaze - 2nd Flr. Window <small>(CAULK)</small>	3% Chry / 2.25 PC
" - #18	Asphalt Shingle - House Roof	ND
" - #19	Plaster Board Joint - 1st. Flr. Front Office Front Wall Corner	2.9% Chry / .75 PC
LAK-2-Parcel 9-#20	Plaster Board Joint - 2nd Flr. S. Office Corner Joint	3% Chry / .50 PC
LAK-2-Parcel 9-#21	Plaster Board Joint - 2nd Flr. Rear Office Corner Joint	2.9% Chry / .75 PC
LAK-2-Parcel 9-#22	Plaster - 2nd Flr. Stairway Center Ceiling	ND

ABBREVIATIONS: ND = Not Detected CHRY = Chrysotile TREM = Tremolite CROC = Crocidolite
 NA = Not Analyzed AMOS = Amosite ACT = Actinolite ANTH = Anthophyllite
 PC = Point Count

SPECIAL NOTES:

SAMPLING BY: Leon Bell Date: 3/21/18

LABORATORY ID#: _____

TRANSPORTED BY: DHL Date: _____

ANALYSIS METHOD: PLM

RECEIVED BY: _____ Date: _____

ANALYZED BY: [Signature] Date: 3/24/18

LEON BELL
 Realty Specialist
 2088 South Adelstein Street
 Akron, Ohio 44306
 Phone 330-468-1130
 Fax 330-786-4879
 Pager 330-914-6046

20