

RE: Parcel 9 - 36628 Vine Street, East Lake, OH

| REG LAB #            | CLIENT ID #          | LOCATION               | COLOR                           |
|----------------------|----------------------|------------------------|---------------------------------|
| 08WB-07108           | LAK2PCL9#10          | 2nd Fir Stairway Steps | Cream/Beige                     |
| Texture/Description: | Solid/Vinyl Flooring | Chrysotile: 0%         | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 0 %                  | Amosite: 0%            | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 10%                  | Fiber Glass: 0%        | Others: 5% Filler/Binder: 85 %  |

| REG LAB #            | CLIENT ID #      | LOCATION              | COLOR                           |
|----------------------|------------------|-----------------------|---------------------------------|
| 08WB-07109a          | LAK2PCL9#11      | 2nd Fir Office Floors | Beige                           |
| Texture/Description: | Solid/Vinyl Tile | Chrysotile: 3%        | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 3 %              | Amosite: 0%           | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 0%               | Fiber Glass: 0%       | Others: 0% Filler/Binder: 97 %  |

| REG LAB #            | CLIENT ID #  | LOCATION              | COLOR                           |
|----------------------|--------------|-----------------------|---------------------------------|
| 08WB-07109b          | LAK2PCL9#11  | 2nd Fir Office Floors | Black                           |
| Texture/Description: | Solid/Mastic | Chrysotile: 3%        | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 3 %          | Amosite: 0%           | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 0%           | Fiber Glass: 0%       | Others: 0% Filler/Binder: 97 %  |

| REG LAB #            | CLIENT ID #        | LOCATION          | COLOR                           |
|----------------------|--------------------|-------------------|---------------------------------|
| 08WB-07110           | LAK2PCL9#12        | 2nd Fir Bath Wall | Bge/Tan/Wht                     |
| Texture/Description: | Solid/Plasterboard | Chrysotile: 0%    | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 0 %                | Amosite: 0%       | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 10%                | Fiber Glass: 0%   | Others: 0% Filler/Binder: 90 %  |

| REG LAB #            | CLIENT ID #   | LOCATION              | COLOR                           |
|----------------------|---------------|-----------------------|---------------------------------|
| 08WB-07111a          | LAK2PCL9#13   | 2nd Fir S Office Wall | Grey                            |
| Texture/Description: | Solid/Plaster | Chrysotile: 2%        | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 2 %           | Amosite: 0%           | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 0%            | Fiber Glass: 0%       | Others: 4% Filler/Binder: 94 %  |

| REG LAB #            | CLIENT ID #    | LOCATION              | COLOR                           |
|----------------------|----------------|-----------------------|---------------------------------|
| 08WB-07111b          | LAK2PCL9#13    | 2nd Fir S Office Wall | White                           |
| Texture/Description: | Solid/Top Coat | Chrysotile: 0%        | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 0 %            | Amosite: 0%           | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 0%             | Fiber Glass: 0%       | Others: 0% Filler/Binder: 100%  |

| REG LAB #            | CLIENT ID #   | LOCATION                | COLOR                           |
|----------------------|---------------|-------------------------|---------------------------------|
| 08WB-07112a          | LAK2PCL9#14   | 2nd Fir Hallway Ceiling | Grey                            |
| Texture/Description: | Solid/Plaster | Chrysotile: 2%          | Tremolite: 0% Anthophyllite: 0% |
| TOTAL ASBESTOS:      | 2 %           | Amosite: 0%             | Actinolite: 0% Crocidolite: 0%  |
| Cellulose:           | 3%            | Fiber Glass: 0%         | Others: 3% Filler/Binder: 92 %  |