

SOIL PROFILE
LAKE COUNTY
LAK-84 (3.27-7.81)
STATE HIGHWAY TESTING AND
RESEARCH LABORATORY
 O. S. U. CAMPUS, COLUMBUS, OHIO

Sta. 154+50 to 158+50, Bad cracking and settlement in superelevated curve.

