

RECORD OF SURVEYS,

Plat of *Survey*, No. *56*, *Wallaughby* Town *9*, Range *10*

Survey made *March 8th & 11th* 1897, at the request of *Township Trustees of Wallaughby Tp*
 For the purpose of *Surveying and marking a Township ditch* in the Township of *Wallaughby*
 by *Grand M. Parker*, County Surveyor.

DESCRIPTION.

Beginning on land owned by *Paige* at a point about 52 rods S eastward from the culvert that crosses the center road. Thence *N 12 1/2° E (5:90)* five chains & twenty links thence *N 35° W (8:10)* eight chains & ten links to the south line of the center road thence at a right angle across the road thence *N 50° W (5:20)* five chains & twenty links thence *N 18° W (5:57)* five chains and fifty seven links thence *N 3° W (2:00)* two chains thence *N 31° W (0:58)* sixty eight links thence *N 70° W (3:40)* three chains & forty links to the road leading to *Walt hill* thence across the road at a right angle & through the culvert, thence *N 80 1/2° W (2:00)* two chains thence *N 89 1/2° W (8:22)* eight chains and twenty two links thence *N 77° W (5:30)* five chains and thirty links to the west line of *L. H. Pikes* land, for more minute details see annexed Plat, and level notes below

Level notes

CALCULATIONS.

Sta.	Course	Distance.		Latitude.		Departure.		Double		Double Areas.		REMARKS.
		I	EL	North Grade	South Remarks	East Sta	West	Inst	EL	North	South	
B.M.	480	48	104.80	100.00								
0	"	"	"	98.5	B.M. top stone at (0)	32	4.0	95.348	91.3			Measurements for levels in chains & links one chain equals 1 station
1	5.1	"	"	98.5		33	4.7		90.6			+ 48 ang
2	5.6	"	"	98.5		34	4.7		90.6			
3	5.6	"	"	98.5		35	5.0		90.3			
4	6.3	"	"	98.5		36	5.1		90.2			
5	6.5	"	"	98.5		37	5.8		89.5			
+ 50	6.6	"	"	98.5		38	6.0		89.3			
6	6.6	"	"	98.5	ang	39	6.2		89.1			
7	7.1	"	"	98.5		40	7.0		88.3			+ 70 angle
8	7.3	"	"	98.5		41	7.1		88.2			
9	7.0	"	"	98.5		42	7.1		88.2			
10	7.0	"	"	98.5		43	7.2		88.1			
11	7.4	"	"	98.5		44	7.8		87.5			
12	7.0	"	"	98.5		45	8.1		87.2			
13	7.6	"	"	98.5		46	8.5		86.8			
14	7.0	"	"	98.5		47	8.9		86.4			Grade at 0 98.5 " turned 85.0 " Ball 13.5
Peg	7.580			98.22	to center road	48				85.0		
"		4.095	101.315		center	49						
+ 50	2.1			99.20	center of culvert road							
15	3.4			99.9								
16	4.5			96.8								
17	5.7			95.6								
18	5.8			96.0								
+ 75	5.7			95.6								
+ 75	5.7			95.6								
20	4.7			96.6								
+ 35	6.5			94.8								
+ 57	6.5			94.8	Grail							
21	6.0			95.3								
22	6.0			95.3								
23	6.0			95.3								
24	7.5			93.7								
25	8.5			92.7								
+ 62	5.2			92.4								
Peg	9.288			92.027								
"		5.043	97.070									
26	5.4			91.7								
27	5.8			91.8								
28	5.9			91.2								
+ 50	6.2			90.9								
29	6.2			90.9								
30	6.9			91.2	474 culvert							
+ 74	6.5			90.6								
31	7.0			93.1	center road							
Peg	6.888			91.205								
"		4.243	95.348									

I, *Grand M. Parker* County Surveyor of *Lake County, Ohio*, do hereby certify, that I have surveyed and subdivided *Lot. No. 4* in *Tract No. 5* Township of *Wallaughby* in accordance with the statutes of *Ohio*, and the laws of the *United States*.
 Surveyed pursuant to the application of *Township Trustees* and *Grand M. Parker* County Surveyor, *March 8th & 11th A. D. 1897*

Grand M. Parker County Surveyor.
S. W. Downing
Fred W. Court Tapemen.

} Flagmen.
 } Markers.

LAKE COUNTY, OHIO.

